

Barco service bulletin

Serial Number: 1381
Date: 20/04/2018
Product: ICMP
Priority code*: C

- A. "Must" modification, Barco will provide the necessary components to perform this modification at no charge.
- B. Improves the reliability of the product.
- C. Improves the general working conditions of the product.
- D. For information only.

1. RTC BATTERY OF THE ICMP NEEDS TO BE REPLACED AFTER 5 YEARS

1.1 General

Phenomenon

The RTC battery of the ICMP will be depleted if kept on stock too long. An empty battery will cause loss of the internal key, will bring the ICMP in the 'FIPS error state' and as a consequence the ICMP board will become non-functional.

Solution

For ICMPs that are kept on stock, change the RTC battery every 5 years. The battery insertion date is labeled on its cover.



ICMPs that are installed in a projector will normally last longer; a timely warning will be generated on an active ICMP installed in the projector when replacement is due.

Scope

All ICMP boards.

Kit needed?

Battery replacement can be done by using the kit R5002007K.

Please following the instructions from section "Replacement of the battery" in your ICMP's service manual.

1.2 Approvals

Modification approved by:

Customer Support
Engineer

R&D Manager

Product Manager

Quality Manager

If you should have any more questions, or remarks, please do not hesitate to contact our technical support team via the following web site www.Barco.com/esupport.